CMS v33.0 study : surface & underground assembly after magnet test

01 Mar 2002 AB