

HITT

The Tacoma Narrows bridge collapsed

- (a) because the design included insufficient damping
- (b) because the materials used were of inferior quality
- (c) because the wind on that day had hurricane force
- (d) because the load on the bridge exceeded design limit
- (e) because it was dynamited